

Contents

Foreword	xi
Acknowledgments	xiii
Introduction	xv

Part 1 Characterizing the Measurement Process 1

Chapter 1 Basic Concepts of Measurement Capability 3

Introduction	4
Figure-of-Merit Statistics	5
The P/T Ratio	5
The SNR	6
RR Percent	6
Six Sigma Quality of Measurement	6
Capability Potential versus P/T and SNR	7
Precision versus Accuracy in a Measurement Tool or Process	11
To Calibrate or Not	16
Understanding Risk	16
JMP Sample Size Calculations and Power Curves	18
Uncertainty in Estimating Means and Standard Deviations	21
Confidence Interval for the Mean	22
Confidence Interval for the Standard Deviation	24
Components of Measurement Error	28
Repeatability Error	28
Reproducibility Error	29
Linearity of Measurement Tools	29
Random versus Fixed Effects	30

Chapter 2 Estimating Repeatability, Bias, and Linearity 17

Introduction	33
Evaluating a Turbidity Meter	33
The Data	33
Determining Bias for Stabcal < 0.1	36
The Paired Analysis	43
Measurement Tool Capability: P/T for Stabcal < 0.1	45
Determining Bias for Gelcal < 10	45
Determining P/T for Gelcal < 10	46
Lessons Learned	47
An Oxide Thickness Measurement Tool	47
Examining the Data	47
Excluding the Questionable Values	51
Generating a Multivari Chart	53
Lessons Learned	56
Repeatability of an FTIR Measurement Tool	56
Examining the First Test	57
Conducting a Second Test	59
Estimating Potential Bias	61
P/T and Capability Analysis	63
Repeatability and Linearity of a Resistance Measurement Tool	66
Reorganizing the Data	67
A Shortcut Method for Evaluating a Measurement Tool	75
Linearity of This Measurement Tool	76
Lessons Learned	77
Using Measurement Studies for Configuring a Measurement Tool	78
Examining the Data	78
Manipulating the Data: Combining the Tables	82
Evaluating the Combinations	85
Lessons Learned	90
No Calibration Standard Available	91
Examining the Data	92
Matched Pair Analysis	93

- Lessons Learned 94
- Exploring Alternative Analyses 94
 - Capability Analyses 95
 - Summarizing Data 96
 - Variance Component Analysis: Using Gage R&R 96
 - Using Regression Analysis 98
 - Lessons Learned 99
- A Repeatability Study Including Operators and Replicates 99
 - Estimating a Figure of Merit: P/T 100
 - Variability Charts: Gage R&R 102
 - Fitting a Model 104
 - Lessons Learned 106
- Summary of Repeatability Studies 108

Chapter 3 Estimating Reproducibility and Total Measurement Error 109

- Introduction 111
- Planning a Measurement Study 112
 - Stating the Objective 112
 - Identifying Potential Sources of Variation 112
 - Gathering the Standard Objects 114
 - Scheduling the Trials 114
 - Generating a Data Entry Form 115
 - Summary of Preparations for a Measurement Study 120
- Analysis of Measurement Capability Studies: A First Example 120
 - Looking at the Data 121
 - Generating a Figure of Merit 123
 - Other Analyses 125
 - Lessons Learned and Summary of the First Example 127
- A More Detailed Study 128
 - Rearranging and Examining the Data 129
 - Measurement Capability 131
 - Summary and Lessons Learned 135
- Turbidity Meter Study 135
 - Examining the Data 136

Estimating Measurement Capability	138
Summary and Lessons Learned	139
A Thin Film Gauge Study	140
Adding a Variable	141
Reordering the Table and Examining the Data	142
Estimating Measurement Capability	143
Fitting Regression Models	147
Lessons Learned	149
A Resistivity Study	149
Examining the Data	150
Estimating a Figure of Merit	153
Fitting a Regression Model	153
Lessons Learned	154
A Final Example	155
Looking at the Data	156
Data Structure and Model Fitting	157
Comparing the Variability Due to OPERATOR	159
Summary and Lessons Learned	160
Summary of Measurement Capability Analyses	162

Part 2 Analyzing a Manufacturing Process 163

Chapter 4 Overview of the Analysis Process 165

Introduction	165
How Much Data?	166
Expected Results from Passive Data Collection	167
Performing a Passive Data Collection	167
Planning the Experiment	167
Collecting the Data	168
Analyzing the Data	168
Drawing Conclusions and Reporting the Results	169

Chapter 5 Analysis and Interpretation of Passive Data Collections 171

Introduction	172
A Thermal Deposition Process	172
Looking at the Data: Initial Analysis of Supplier-Recommended Monitor Wafers	174
Analysis of the Team-Designed Sampling Plan	176
Reporting the Results	179
Lessons Learned	180
Identifying a Problem with a New Processing Tool	181
Looking at the Data: Estimating Sources of Variation	181
An Alternative Analysis	185
Lessons Learned	188
Deposition of Epitaxial Silicon	189
Determining a Sampling Plan	189
Analyzing the Passive Data Study	191
Lessons Learned	196
A Downstream Etch Process	196
Overview of the Investigation	196
Passive Data Collections	197
Lessons Learned	207
Chemical Mechanical Planarization	208
Polishing Oxide Films	208
Polishing Tungsten Films	217
Polishing a Second Type of Oxide Film	222
Summary of Passive Data Collections	230

Part 3 Developing Control Mechanisms 231

Chapter 6 Overview of Control Chart Methodology 233

Introduction	234
General Concepts and Basic Statistics of Control Charts	235
Types of Data	235
The Normal Distribution	236
How Many Samples?	236
Examination of Data	237
Types of Control Charts and Their Applications	237
Charts for Variables Data	237
Charts for Attributes Data	245
Special Charts for Variables Data	249
Trend Analysis	252
The Western Electric Rules	253
The Westgard Rules	254
Implementing Trend Rules	255
Capability Analysis	256
The Cp Statistic	256
The Cpk Statistic	258
The Cpm Statistic	260
Generating Capability Statistics in JMP	261
Control Charts Involving Non-Normal Data	261
Summary	261

Chapter 7 Control Chart Case Studies 263

Introduction	264
Measurement Tool Control	264
Some Scenarios for Measurement Tool Control Charts	266
Replicated Measurements at a Single Sample Site	267
Summary of the First Example	275
Measurements across an Object—No Replicates	275
Summary of the Second Example	279
A Measurement Study with Sample Degradation	280

Summary of Control Charting Issues for Measurement Tools	286
Scenarios for Manufacturing Process Control Charts	287
A Single Measurement on a Single Object per Run	289
An Application for XBar and S Charts?	294
A Process with Incorrect Specification Limits	302
Multiple Observations on More Than a Single Wafer in a Batch	305
Dealing with Non-Normal Data	316
The SEMATECH Approach	316
Monitoring D0	317
Cleaning Wafers (Delta Particles)	322
Defective Pixels	328
Summary of Control Chart Case Studies	332

References 335

Index 337

